



# UP KOSTIĆI - URBANISTIČKI USLOVI

**UP 477**


# URBANISTIČKI PARAMETRI PARCELE

br. parc.	namjena	P parcele	br. obj. na parc.	P osnove obj.	spratnost	BRGP	intervencija	opis intervencije
	postojeći objekat		1	96	P+1	191	rekonstrukcija ruševine	SK razvijena spratna kuća - u svemu prema zatečenom rješenju
UP477	SMG	96	1	96	P+1	191		




IDEJNO RJEŠENJ


R=1:200



JUŽNA FASADA



## OSNOVA SPRATA




A photograph showing a long, low stone wall made of rough-hewn stones. The wall is covered in thick green ivy and other leafy plants, particularly on the right side where it rises into a hillside. In the center-left, there is a small, open doorway with a green frame. Above the doorway, there is a brick chimney or a small arched opening. To the left of the doorway, a set of wooden steps leads up to a small building with a red door. The ground in front of the wall is a paved path made of large, irregular stones. The sky is clear and blue.



## OSNOVA PRIZEMLJA



## ISTOČNA FASADA



PRESJEK A - A



Foto - segment južne fasade